Troubleshooting

(BT shank for stub holder)

	Details of the trouble	Cause	Pulled out of holder. Unable to attach fast to spindle or holder in case of MT shank.
1	Cannot insert coolant pin. (In the case of KH/BH)	① Selection of coolant pin size is not correct.	① Check size.
		② The size selected is of the size that coolant pin cannot be inserted.	② Check size; there are sizes that do not allow center-thru coolant supply.
2	Cannot insert stub holder.	① Sizes do not match between BT shank for stub holder and stub holder.	① Check shank size and stub holder size.
		② Seized or adhered chip and dust to stub holder shank, BT shank for stub holder I.D	② Cleaning of stub holder shank, BT shank for stub holder I.D
		③ Scratch or dent exists in BT shank for stub holder I.D. or stub holder shank.	 (3) Replace stub holder or repair BT shank for stub holder. Touching up of area in question (rubbing off with sand paper #1000 and above) Correction (grinding) by NT TOOL is not possible.
			④ Make thickness of aspacer adjust to specified dimension.
		 (4) In the case of KD/BT series, end face to end face dimension between shank and finger bolt is longer than specified dimension. (When replacing finger collets) 	
2		(1)	(1)
3	Excessive play when mounting into spindle.	In the case of KH series, spindle mounting is not proper due to functional failure of operating sleeve.	 When installing, push operating sleeve down to bring it into position for secure mounting. Cleaning of operating sleeve I.D
		② In the cases of KH-A, KH series, rubber damper is deteriorated.	② Ask NT for repair.
		③ In the case of KH-E series, steel ball is worn.	③ Ask NT for repair.
		④ In the case of KD/BT, end face to end face dimension between shank and finger bolt is shorter than specified dimension.	④ Make thickness of aspacer adjust to specified dimension.
		(When replacing finger collets)	⑤ Replacement of finger collet assembly.
		(5) In the case of KD series, finger collet taper is worn.	6
		(6) In the case of KD series, finger collets are broken.	Replacement of finger collet assembly.
4	Chattering	(1)	
+	Chattening	Cutting resistance is too high in comparison with holder's rigidity.	 Revision of cutting conditions (Decrease cutting resistance.) a : Higher rotation speed or lower feed rate (Approx. 20%) b : Lower cutting depth Shorter tool projection length
		② When end-milling with KH-E, cutting pressure is too low against holder rigidity.	 (2) Revision of cutting conditions (Increase cutting resistance.) a : Higher feed rate or lower rotation (Approx. 20%) b : Higher cutting depth
		3	③ Shorter tool projection length

		Bending moment is too large. ④ Stub holder is mounted improperly with play.	(e) See Trouble: "Excessive play when mounting into spindle" and remove play.
5	Poor machining accuracy.	 Insult to mean of improperty that puty. BT shank for stub holder and stub holder have rattling. Adhered chip and dust to BT shank for stub holder end surface or stub holder end surface. Poor chucking accuracy of collet. Dust seizing in collet insertion area. Scratch or dent in holder I.D Scratch or dent on collet I.D. and O.D Insufficient chucking length. Poor accuracy of tool. Dust seizing in cap nut thread. Malfunction of rotor ring of cap nut (Rotor ring will not rotate smoothly.) 	 See Trouble: "Excessive play when mounting into spindle" and remove play. Cleaning of BT shank for stub holder end surface or stub holder end surface. Replacement of collets Cleaning of collet insertion area. Replacement of holder. Replacement of collets. Iterational area. Replacement of collets. Replacement of collets. Replacement of collets. Iterational area. Replacement of collets. Iterational area. Replacement of collets. Iterational area. Iterational area.
		 Mischoice of retention stud. Image: Mischoice of BT shank because of over-tightening retention stud. 	 Replacement of cap nuts. ① Use designated retention stud for the machine. ② Keep recommended torque valuefor tightening retention stud.
6	Holder does not come off from spindle.	 Deposition of fretting, rust and/or adhered coolant residual. (2) In the case of KH series, operating sleeve failure. 	 Cleaning of BT shank for stub holder I.D. and stub holder shank. Cleaning of operating sleeve I.D