Troubleshooting (Hyper spindle)

	Contents of the trouble	Causes	Pulled out of holder. Unable to attach fast to spindle or holder in case of MT shank.
1	Unusual noise	① wear and bearing life	① Ask NT for repair.
		②	②
		wear and breakage of gears ③	Ask NT for repair. ③
		"A" dimension is not right	•Check "A" dimension (plunger's height)
			•Dust or chip on the contact face of positioning block.
2	Deteriorated accuracy during cutting	① "A" dimension (plunger's height) is not correct.	① •Check "A" dimension (plunger's height).
	(Guidelines: 30 micrometers/4D and above)		•Dust or chip on the contact face of the positioning block.
		② Poor chucking accuracy of collet	② •Replacement of collets
		roof chucking accuracy of conet	•AA grade collet should be used.
		③ Penetrated dust in collet installation part	③ Cleaning of collet insertion area
		④ Insufficient chucking length	Keep minimum insertion length of tool.
		©	(5)
		Tool shank end touches the bottom of chuck ID	Tool shank end must be detached from the bottom of the chuck. (Otherwise, chucking accuracy will be deteriorated.)
		©	⑥ Replacement of tools
		Poor accuracy of tool ⑦	⑦
		Dust seizing in cap nut thread	Cleaning and greasing of thread area
		Malfunction of rotor ring of cap nut(Rotor ring rotation is not smooth.)	Cleaning of cap nut (so that the rotor ring will rotate smoothly) Replacement of cap nuts
		Expansion of BT shank because of overtightening retention stud	Keep recommended torque value for tightening retention stud.
		0	(1)
		Deteriorated accuracy of tool interface Large runout (2 micrometers and above) of spindle ID or	Regrinding or correction of machinespindle
		end face (in the case of two-face contact) • Dust, scratch or dent on taper area or end face (in the face of two-face contact)	Cleaning of taper and end face (in the case of two-face contact), touching up of scratch or dent
	Cutting tool is pulled out during cutting	① Insufficient tightening of cap nut	*Keep recommended torque value for tightening cap nut.
			•Use torque wrench.
		② Insufficient tightening from malfunction of rotor ring in the cap nut	② Replacement of cap nuts
		③ Insufficient tightening of cap nut because of incresaed friction in the thread part	③ Apply oil (grease) on the thread part after cleaning it.
		④ Cutting resistance is large. (Pullout by pestle-like movement)	④ Decrease cutting resistance. a. Lower tool projection length b. Higher rotation or lower feed rate (Approx. 20%) c. Lower cutting depth

4	Chattering	① Chattering by holder's resonance	① Shift rotation speed (more than 10%)
		② Cutting resistance is too low in comparison with holder's rigidity.	② Revision of cutting conditions (Decrease cutting resistance.) a. Higher rotation or lower feed rate (Approx. 20%) b. Lower cutting depth
		③ Bending moment is too large.	③ Lower tool projection
		Poor contact of unterface Lost contact because of spindle expansion Dust, scratch or dent of taper area or end face (two-face contact)	Correction of machine spindle by regrinding Cleaning of taper and end face (in the case of two-face contact), touching up of scratch or dent.
		⑤ Mischoice of retention stud	⑤ Use designated retention stud for the machine.
		(6) Expansion of BT shank because of overtightening retention stud	© Keep recommmended torque value for tightening retention stud.