

Troubleshooting

(Multibore tooling system)

	Details of the trouble	Cause	Pulled out of holder. Unable to attach fast to spindle or holder in case of MT shank.
1	Insert cannot be mounted	<p>① Designated insert is not used.</p> <p>② Designated insert mounting bolts are not used.</p>	<p>① Use designated insert.</p> <p>② Use designated mounting bolts.</p>
2	Cannot adjust diameter.	<p>① Adjustment is being made with lock bolt tightened.</p> <p>② Exceeding adjusting range.</p>	<p>① Adjust with lock bolt loosened.</p> <p>② Adjust within the adjusting range.</p>
3	Master shank and head do not come together.	<p>① Wrong size.</p> <p>② Abrasion of clamp bolt.</p> <p>③ Deposition of chips, dust, rust and coolant residual on the connecting portions of master shank and head.</p> <p>④ Scratches and/or dent on connecting portions of master shank and/or head (I.D., end face)</p>	<p>① Check size.</p> <p>② Replacement of clamp bolt.</p> <p>③ Clean connecting portions of master shank and head.</p> <p>④ Replace master shank and/or head.</p>
4	Chattering	<p>① Cutting resistance is too high in comparison with holder's rigidity.</p> <p>② Lock screw is loose.</p> <p>③ Inappropriate tool tip clamping. •Dust seizing. •Designated insert mounting bolts are not used.</p> <p>④ RPM is too high.</p> <p>⑤ Abrasion or deposition of insert.</p> <p>⑥ Tip nose R is too large against cutting feed. (Because of large thrust force.)</p> <p>⑦ Scratches and/or dent on connecting portions of master shank and/or head (I.D., end face)</p> <p>⑧ Weakened rigidity due to multiple use of extensions.</p> <p>⑨ Fastening effectiveness not enough due to clamp bolt wear.</p> <p>⑩ Deposition of chips, dust, rust and coolant residual on the connecting portions of master shank and head.</p> <p>⑪ In the case of twin cutter head, runout is too large.</p>	<p>① •Revision of cutting conditions (Decrease cutting resistance.) a : Higher rotation speed or lower feed rate (Approx. 20%) b : Lower cutting depth •Shorter tool projection length</p> <p>② Tighten lock screw.</p> <p>③ •Cleaning of insert seat. •Use designated mounting bolts.</p> <p>④ Reduce RPM.</p> <p>⑤ •Replacement of insert. •When adhesion occurs, increase RPM.</p> <p>⑥ Replace tip with one having smaller nose R.</p> <p>⑦ Replace master shank and/or head.</p> <p>⑧ •Reduce number of extensions. •Use reduction to increase master shank size to maintain rigidity required.</p> <p>⑨ Replacement of clamp bolt.</p> <p>⑩ Clean connecting portions of master shank and head.</p> <p>⑪ Reduce runout.</p>

5	Loosened clamp bolt and insert holder mounting bolt.	<p>① Deposition of chips, dust, rust and coolant residual on the connecting portions of master shank and head.</p> <p>② Bolt tightening is not enough.</p>	<p>① Clean connecting portions of master shank and head.</p> <p>② Tighten bolt.</p>
6	Coolant is not supplied.	<p>① Mischoice of retention stud.</p> <p>② Using head that is not compatible with coolant.</p>	<p>① Use designated retention stud for the machine (Coolant specification).</p> <p>② Check type of head being used: some heads are not compatible with center-thru coolant.</p>
7	Poor machining accuracy.	<p>① Cutting resistance is too high in comparison with holder's rigidity.</p> <p>② Lock screw is loose.</p> <p>③ Inappropriate tool tip clamping. •Dust seizing. •Designated insert mounting bolts are not used.</p> <p>④ RPM is too high.</p> <p>⑤ Abrasion or deposition of insert.</p> <p>⑥ Scratches and/or dent on connecting portions of master shank and/or head (I.D., end face)</p> <p>⑦ Deposition of chips, dust, rust and coolant residual on the connecting portions of master shank and head.</p> <p>⑧ In the case of twin cutter head, runout is too large.</p>	<p>① •Revision of cutting conditions (Decrease cutting resistance.) a : Higher rotation speed or lower feed rate (Approx. 20%) b : Lower cutting depth •Shorter tool projection length</p> <p>② Tighten lock screw.</p> <p>③ •Cleaning of insert seat. •Use designated mounting bolts.</p> <p>④ Reduce RPM.</p> <p>⑤ •Replacement of insert. •When adhesion occurs, increase RPM.</p> <p>⑥ Replace master shank and/or head.</p> <p>⑦ Clean connecting portions of master shank and head.</p> <p>⑧ Reduce runout.</p>